

# BULLETIN OF EARTHQUAKE RESISTANT STRUCTURE RESEARCH CENTER

No.33  
MARCH 2000

## Contents

<b>Foreword</b>	K. Ohi, Dr. Eng. ....	1
<b>Papers</b>		
LAT/PSC Test for Microscopic Observation of Three-Dimensional Granular Fabric T. Ishii, T. Matsushima and K. Konagai .....	3	
Liquefaction Tests with Hollow-Cylindrical Torsional Shear Apparatus under Low Confining Stress J. Koseki, D. Itakura, S. Kawakami, T. Sato, K. Hayano and M. Torimitsu .....	11	
Preliminary Report on Damage to Retaining Walls Caused by the 1999 Chi-Chi Earthquake J. Koseki and K. Hayano .....	23	
A Proposal for Method for Detection of Soil Liquefaction Using Strong Motion Records M. V. Kostadinov, F. Yamazaki and K. Sudo .....	35	
Estimation of a Relation between Quality Factors and Standard Penetration Resistance using the Somp Method P. Mayorca, T. Ishii and K. Sudo .....	47	
Deformation Build Up in Soils and Damage to Viaduct Foundations H. Kamiya and K. Konagai .....	57	
Buildup Soil Deformation and Dmage to Subway Tunnels S. Nishiyama, A. Nishimura and K. Konagai .....	65	
Earthquake and Impulse Response Tests on a Steel Frame Strengthened by Fully Mechanical Braces K. Ohi, K. Takanashi, S. J. Lee, Y. Shimawaki, H. Ohtsuka and H. Imazu.....	73	
Inelastic Behaviors of End-plate Connections during Earthquakes and Improvement on their Rotation Capacity K. Ohi, S. J. Lee, Y. Shimawaki, H. Ohtsuka and R. Guzman .....	81	
Experimental Studies about Wave Propagation Properties of Single Layer Lattice Structures - Cantilever Beams and Lattice-Type Plates - P. Liu, A. Nishida and K. Kawaguchi .....	87	
Development of Quick Damage Inspection Method of Jacketed Viaduct Using Microtremor Measurement & Numerical Simulation F. Uehan and K. Meguro .....	97	
Improvement on Quick Inspection Method for Damaged RC Structures Using Applied Element Method F. Uehan and K. Meguro .....	109	
Comparison of Empirical and Analytical Fragility Curves for Highway Bridge Piers K. R. Karim and F. Yamazaki .....	117	
Method for Building Collapse Risk Assessment based on Actual Damage Data due to The 1995 KOBE Earthquake O. Murao, H. Tanaka, F. Yamazaki, and K. Wakamatsu.....	129	
AIJ Technical Guide for Temporary Restoration of RC School Buildings Damaged by 921 Chichi Earthquake Y. Nakano .....	139	
<b>List of Papers by Members of Earthquake Resistant Structure Research Center</b> .....	153	
<b>News</b> .....	161	
<b>Meetings of Earthquake Resistant Structure Research Center</b> .....	167	

**INSTITUTE OF INDUSTRIAL SCIENCE  
UNIVERSITY OF TOKYO**

