

BULLETIN OF EARTHQUAKE RESISTANT STRUCTURE RESEARCH CENTER

No. 42
MARCH 2009

Contents

Foreword	1
Papers	
A Quantitative Approach to Assess Landform Changes of Hattian Ballah Landslide Dam Formed by 2005 Kashmir Earthquake K. Ahsan SATTAR, Kazuo KONAGAI, Takaaki IKEDA, Takashi KIYOTA, Zaheer Abbas KAZMI, Masahiro KOIKE	3
Slope Failure Induced Debris Flow Hazards in the October 8, 2005, Kashmir Earthquake Zaheer Abbas KAZMI, Kazuo KONAGAI, Takaaki IKEDA, Takashi KIYOTA, Koichi KONDO, Ahsan SATTAR	17
Geotechnical Issues Caused by The May 12 th 2008, Wenchuan Earthquake, China Kazuo KONAGAI, Yoshiharu ISHIKAWA, Satoshi TSUCHIYA and Fawu WANG	33
Provisional Report of The Damage Caused by The June 14 th 2008, Iwate-Miyagi Earthquake Kazuo KONAGAI, Tomohiro FUJITA, Fumihiko NOMURA, Yuriko TOMIYASU, Masaki DATE, Yoshimitsu TAJIMA and Toshihiko KATAGIRI	43
Building Damage due to 2008 Wenchuan Earthquake and Cooperative Activities on Damage Restoration by Japanese Experts Yoshiaki NAKANO, Masaki MAEDA, Joji SAKUTA, and Masanobu SAKASHITA	51
Effect of Static Shear Stress on Undrained Cyclic Behavior of Saturated Sand Gabriele CHIARO, Takashi KIYOTA, L.L.N. DE SILVA, Takeshi SATO and Junichi KOSEKI	63
A Cyclic Elasto-Plastic Constitutive Model to Describe Drained and Undrained Torsional Shear Behavior of Sand Laddu Indika Nalin DE SILVA, Junichi KOSEKI and Takeshi SATO	73
Use of Granular Material Made from Recycled Glass as Countermeasure Against Earthquake-Induced Uplift of Underground Pipes Tomonori MIKAMI, Junichi KOSEKI, Takeshi SATO and Chihiro YAJIMA	87
Survey on Damage to Roads in Akita Prefecture Caused by 2008 Iwate-Miyagi Nairiku Earthquake Yukika TSUTSUMI, Junichi KOSEKI, Reiko KUWANO, Takashi KIYOTA and Tomonori MIKAMI	97
Small Strain Shear Stiffness of Toyoura Sand Obtained from Various Wave Measurement Techniques Ruta Ireng WICAKSONO and Reiko KUWANO	107
Formulation of A Simple Method to Design PP-Band Mesh Retrofitting for Adobe/Masonry Houses Paola MAYORCA and Kimiro MEGURO	121
Dynamic Behavior of Timber Roof Masonry House Models Retrofitted by PP-Band Meshes Navaratnarajah SATHIPARAN, Paola MAYORCA and Kimiro MEGURO	131
Damage to non-structural components in large roof buildings by two MAJOR earthquakes occurred in the northeastern region of Japan in 2008 Ken'ichi KAWAGUCHI, Yoshiro OGI, Shunji OHYA, Shin'ichiro KATAYAMA, Shogo KUMAGAI and Shigeyoshi SAKURAI	141
List of Papers by Members of Earthquake Resistant Structure Research Center	153
News	169
Meetings of Earthquake Resistant Structure Research Center	177



**INSTITUTE OF INDUSTRIAL SCIENCE
UNIVERSITY OF TOKYO**

<http://shake.iis.u-tokyo.ac.jp/ERS/>